


Replaces Toro Greensmaster 3050 Parts



SPA Cutting Unit - Models 04478 Minuteman Roller System





Replaces Toro Greensmaster 3050 Parts



SPA Cutting Unit - Models 04478 Minuteman Roller System

	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
Comp	olete Minutema	n Roller Systems			
1	RMT8001		Minuteman Front Grooved Roller System	0	
	Tech Note: Com	plete roller systems i	nclude roller and two brackets with bearings.:		
Minu	teman Rollers (Only			
2	RM513		Minuteman Grooved Roller Only	0	
	Tech Note: Use	with Minuteman Roll	er Bracket System Only:		
Other	r Parts Availabl	e			
3	RT821		Bracket Assy - Front LH/RH	2	
	Tech Note: Includes RT8210 Bearing & Locking Collar, RMM606 Washer, R3219-5 Nut & RMM607 Screw:				
4	RMMB157		Bearing w/Locking Collar	2	
5	RT8210		Block - Height Adj	2	
6	RMM606		Washer - Lock 3/8 Zinc Internal Tooth	2	
7	R3219-5	01-188-0820, 22-15-BJD, 22-15-BJKD, 3219-5	Nut - 1/2-20	4	
8	RMM607	01-158-0610, 01-191-0820, 21-3900, 3220-5, 45-0170, 5/1/3220	Nut - Jam 1/2-20 Zinc	2	
9	RMM608		Screw - 8-32 x 5/16 SS Socket Head	2	
10	RMM3		End Hub - 7/8 ID	2	
11	RT821P		Plate - For RT821 Bracket	2	
12	RT821B		Ball - For RT821 Bracket	2	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Greensmaster 3050 Parts



SPA Cutting Unit - Models 04478 Minuteman Roller System