




Replaces Toro Greensmaster 3050 Parts

SPA Cutting Unit - Models 04472, 04473, 04482 & 04483
Minuteman Roller System



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Greensmaster 3050 Parts

SPA Cutting Unit - Models 04472, 04473, 04482 & 04483
Minuteman Roller System



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
Complete Minuteman Roller Systems					
1	RMT3201		Minuteman Front Grooved Roller System	0	
<i>Tech Note: Complete roller systems include roller and two brackets with bearings.:</i>					
Minuteman Rollers Only					
2	RM511		Minuteman Grooved Roller Only - 22 in	0	
<i>Tech Note: Use with Minuteman Roller Bracket System Only:</i>					
Other Parts Available					
3	RT321		Bracket - Front	2	
4	RMMB157		Bearing w/Locking Collar	2	
5	RMM3		End Hub - 7/8 ID	2	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.