



NGK Spark Plug - R7435-10

RN4897



Replaces

Autolite	4051
----------	------

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Evergreen

C/. Bartomeu Amat, 2, Entlo 1 Terrassa, 08225
+34 931 130 054

<https://evergreen.rrproducts.com/>