



## Replaces Toro Workman HDX Parts

Traction Unit - 2WD Models 07383 & 07384

Steering & Controls



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Workman HDX Parts

Traction Unit - 2WD Models 07383 & 07384

Steering & Controls



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|--------------|--------------|-------------|---------|----------------|
|---------|--------------|--------------|-------------|---------|----------------|

## Filters

|    |                 |         |                 |   |  |
|----|-----------------|---------|-----------------|---|--|
| 12 | <b>R46-7510</b> | 46-7510 | Hood-Inlet- Air | 1 |  |
|----|-----------------|---------|-----------------|---|--|

## Guages and Controls

|    |                  |                    |                                                      |   |  |
|----|------------------|--------------------|------------------------------------------------------|---|--|
| 30 | <b>R151541</b>   | R&R ON, LY         | Delta Seat Switch - Twist Mount 1 Pole Normally Open | 1 |  |
| 31 | <b>R105-0023</b> | 105-0023           | Sensor - Proximity                                   | 1 |  |
| 32 | <b>R100-1270</b> | 100-1270           | Sensor - Proximity                                   | 1 |  |
| 33 | <b>R99-7430</b>  | 99-7430            | Relay - 30 Amp                                       | 1 |  |
| 34 | <b>R95-8999</b>  | 95-8999            | Switch - Headlight                                   | 1 |  |
| 35 | <b>R120-4813</b> | 120-4813           | Steering Pump                                        | 1 |  |
| 36 | <b>R151386</b>   | 106-5269, 121-5159 | Ignition Switch Assy                                 | 1 |  |
| 37 | <b>R100-4918</b> | 100-4918           | Diode                                                | 1 |  |

## Other Parts Available

|    |                  |                                        |                          |   |  |
|----|------------------|----------------------------------------|--------------------------|---|--|
| 70 | <b>RMXB180GY</b> | 106-6672, 112-2923, 119-8829, 133-0577 | Milsco Seat XB180 - Grey | 2 |  |
|----|------------------|----------------------------------------|--------------------------|---|--|

*Detail Description: The Milsco XB180 bucket seat is designed with a sturdy vacuum formed waterproof vinyl cover that will not crack or peel. Ergonomic foam cushions ensure operator comfort. Features a durable blow molded plastic frame. Allows for an operator presence switch. Central drain hole prevents water build-up. 19 inch high-back seat will replace both original 16in and 19in high-back seats. Seat: 18.75in W x 18.8in H. Grey. Made in U.S.A. <BR>Please note: Due to excessive air freight charges, this item will be shipped ground freight.:*

|    |                 |                           |                                      |    |  |
|----|-----------------|---------------------------|--------------------------------------|----|--|
| 71 | <b>R98-1471</b> | 93-5212, 94-3500, 98-1471 | Steering Wheel Assy - 14 in Incl Cap | 1  |  |
| 72 | <b>R98-1468</b> | 98-1468                   | Cap - 14" Steering Wheel             | 1  |  |
| 73 | <b>R3234-29</b> | 3234-17, 3234-29          | Bolt - 5/16-18x1 Serr Hex            | 10 |  |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Workman HDX Parts

Traction Unit - 2WD Models 07383 & 07384

Steering & Controls



| Item No | R&R Part No. | OEM Part No.                                                                                                                                   | Description                      | Qty Req | Order Quantity |
|---------|--------------|------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|---------|----------------|
| 77      | R150848      | 100-4928,<br>106-7848,<br>110-0413,<br>110-9720,<br>95-8910                                                                                    | Belt-Seat                        | 2       |                |
| 78      | R2412-133    | 01-651-0160,<br>2412-133                                                                                                                       | Clamp                            | 1       |                |
| 79      | R3234-11     | 3234-11                                                                                                                                        | Bolt - Hex Washer HD             | 1       |                |
| 80      | R3212-4      | 3212-3,<br>3212-4,<br>3212-5                                                                                                                   | Bolt - Hex HD 7/16-20 x 1<br>GR5 | 2       |                |
| 81      | R99-7420     | 100-8493,<br>99-7420                                                                                                                           | Plug-Hole                        | 3       |                |
| 82      | R150224      | 106-7847 & 107-7959,<br>107-7959,<br>119-0654 & 119-0655,<br>133-8896,<br>192-8990 & 92-8991,<br>92-8990,<br>92-8990/92-8991,<br>92-8991       | Adjusters - Seat (Set of 2)      | 2       |                |
| 83      | R106-2475    | 106-2475                                                                                                                                       | Brake Shaft Assy                 | 1       |                |
| 84      | R63-3410     | 63-3410                                                                                                                                        | Screw - Shoulder                 | 2       |                |
| 85      | R256-156     | 256-156,<br>256-219                                                                                                                            | Bushing - Flanged                | 4       |                |
| 86      | R302-5       | 21-6010,<br>302-11,<br>302-37,<br>302-47,<br>302-5,<br>302-57,<br>302-58,<br>302-6,<br>31-0300,<br>32-9660,<br>60-0800,<br>62-3880,<br>92-4181 | Fitting - Grease                 | 2       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



## Replaces Toro Workman HDX Parts

*Traction Unit - 2WD Models 07383 & 07384*

*Steering & Controls*



| Item No | R&R Part No.     | OEM Part No.         | Description                      | Qty Req | Order Quantity |
|---------|------------------|----------------------|----------------------------------|---------|----------------|
| 87      | <b>R98-7977</b>  | 98-7977              | Bolt- Hx Serr Fl HD M8-1.25 x 20 | 4       |                |
| 88      | <b>R115-2283</b> | 115-2283             | Cable - Parking Brake            | 2       |                |
| 89      | <b>R3296-12</b>  | 32127-20,<br>3296-12 | Nut - 10-32 Nylon Lock           | 2       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.